

CTAF INBOUND CALL at 10NM (18.5km):

- 1. "TEMORA TRAFFIC"
- 2. GLIDER Alpha Bravo Charlie
- 3. POSITION (e.g. 10 miles south west)
- 4. *INTENTION* (e.g. inbound or overflying & track)
- 5. HEIGHT QNH (feet above MSL)
- 6. "TEMORA"



CTAF 126.15

AWIS 134.45

or 02 9353 6453

Vehicles airside must stay below 25 kph, and:

Operate rotating or flashing roof mounted light

Operate vehicle hazard lights

Stay outside runway strips if not towing glider

Stop and look before crossing runway strip ends

NOT enter runway strips to retrieve glider

Vehicles towing gliders must, in addition:

Monitor and communicate on CTAF 126.15

Exercise good LOOKOUT at all times and in ALL directions

NOT cross runways unless airspace is cleared by good <u>LOOKOUT</u> in <u>ALL</u> directions

Landing gliders make circuit calls on CTAF 126.15, and:

Fly left hand circuits to all runways when possible

Taxi to dead side of runway in predictable way

Move glider clear of runway strip promptly before vehicle retrieve

Contacts:

Temora Gliding Club - President (Paul Wiggins)

0422 138891

Temora Gliding Club - CFI (Grant Johnson)

0429 985506

Temora Gliding Club - Safety Officer (Mike Cleaver)

0403 840607